

SSO Notification List

January 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	1/1/2015	2500 Frederick Ave	21223	Rags, Grease	DWO	Inner Harbor	63	Sewage flowing from the eyes of the manhole	315	Relieved with pressure jet truck	CCTV	221757
2	1/1/2015	3110 Falt Ave	21224	Rags, Grease	DWO	N/A	90	Sewage flowing from the eyes of the manhole	45	Used Sewer Jet	CCTV	221766
3	1/2/2015	3106 Harford Rd	21218	Pipe Break	DWO	N/A	Not Witnessed	Observed Sewer Water around clean out	Evidence of Overflow	Used Electric machine	CCTV	221898
4	1/2/2015	4321 Park Heights Ave	21215	Rags, Grease	DWO	N/A	111	Cloudy water	111	Relieved choke with 30' Electric machine	CCTV	221846
5	1/2/2015	4823 Herring Run Dr	21214	Rags, Roots, Grease	DWO	N/A	Not Witnessed	Gray colored water	Evidence of Overflow	Cleaned area with pressure truck	CCTV	221841
6	1/4/2015	5532 Plainfield Ave	21206	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Evidence of spillage, paper around clean out	Evidence of Overflow	Relieved choke with electric machine	CCTV	221965
7	1/5/2015	1012 Billie Holiday Ct	21205	Rags, Grease	WVO	N/A	Not Witnessed	Water on grass yard	Evidence of Overflow	Used electric machine and sewer jet to relive choke	CCTV	222135
8	1/5/2015	5110 Windsor Mill Rd	21207	Other	WVO	N/A	Not Witnessed	Mud and water on lawn	Evidence of Overflow	Used electric machine to relieve choke	CCTV	222132
9	1/5/2015	15 Edgevale Rd	21210	Rags, Grease	WVO	N/A	143	Sewage overflowing and running into the storm inlet	715	Relieved mainline choke with pressure truck, 50 ft of 6"	CCTV	220025
10	1/6/2015	1015 N Mount St	21217	Rags, Grease	WVO	N/A	Not Witnessed	Cloudy water	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	222836
11	1/8/2015	4720 York Rd	21212	Grease, Trash, Sand, Gravel, Rocks	DWO	Tiffany Run	223	Choked sanitary causing sewage to flow into storm drain	223	Jetted line with pressure truck	CCTV the mainline	223637
12	1/9/2015	1220 Bayard St	21230	Rags, Other	DWO	N/A	Not Witnessed	Ground is wet around clean out	Evidence of Overflow	Used electric machine to relieve choke	CCTV	223763
13	1/9/2015	1510 Guildford Ave	21202	Rags, Grease	DWO	N/A	Not Witnessed	Grease on top of manhole	Evidence of Overflow	Used sewer jet to relieve choke	CCTV	223748
14	1/9/2015	1912 Ramsay St	21223	Trash, Sand, Gravel, Rocks, Other	DWO	N/A	Not Witnessed	Evidence of debris around the clean out	Evidence of Overflow	Mainline clear	Spoke to consumer about clean out issue	
15	1/13/2015	2103 Brookfield Ave	21217	Rags, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Sewer water & toilet paper in and around clean out	Evidence of Overflow	Ran electric machine, 30 ft cable	CCTV	224179
16	1/13/2015	2305 Whittier Ave	21217	Roots, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Toilet paper around clean out	Evidence of Overflow	Ran 45 ft of electric machine to clear choke	CCTV	224225
17	1/13/2015	434 S Hanover St	21201	Rags	WVO	N/A	Not Witnessed	Gray water around clean out area	Evidence of Overflow	Ran electric machine, used 75 ft cable	CCTV	224206
18	1/13/2015	1132 W Saratoga St	21223	Rags, Grease	WVO	N/A	Not Witnessed	Evidence and debris around clean out	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	224278
19	1/13/2015	2717 Marbourne Ave	21230	Rags, Roots	WVO	N/A	Not Witnessed	Evidence in and around clean out	Evidence of Overflow	Relieved house connection choke using 30ft electric machine	CCTV	224214
20	1/15/2015	977 Ellicott Driveway	21216	Rags, Roots, Grease	DWO	Gwynns Falls	780	Heave Gray Water	19,500	Relived ML choke with pressure truck 50' of 8"	T/O to CCTV and Sewer Rodder	224882
21	1/15/2015	3106 Harford Rd	21218	Trash, Sand, Gravel, Rocks, Other	DWO	N/A	Not Witnessed	Gray water around clean out area, evidence of an overflow	Evidence of Overflow	Relieved choke with electric machine	CCTV	224754
22	1/15/2015	3128 Weaver Ave	21214	Roots	DWO	N/A	Not Witnessed	Frozen paper, evidence of overflow	Evidence of Overflow	Used electric machine to clear choke	CCTV	224825
23	1/16/2015	1008 Poplar Hill Rd	21210	Rags, Roots	DWO	N/A	285	Heavy Gray Water	570	Relived ML choke with pressure truck 75'	CCTV	224881

SSO Notification List

January 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
24	1/16/2015	3300 Reisterstown Rd	21215	Rags	DWO	N/A	125	Heavy Gray Water	250	Relieved ML choke with pressure truck 150 ft	T/O to CCTV	224886
25	1/16/2015	4309 Groveland Ave	21215	Rags	DWO	N/A	Not Witnessed	Toilet paper in and around clean out	Evidence of Overflow	Ran 30ft of electric machine to relieve choke	CCTV	224891
26	1/17/2015	316 E 22nd St	21218	Rags, Grease	DWO	N/A	Not Witnessed	Evidence of overflow around clean out	Evidence of Overflow	Relieved house connection choke with electric machine, 45 ft	CCTV	225061
27	1/17/2015	4030 Deepwood Rd	21218	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	150	Heavy gray water at location	300	Relieved mainline choke with pressure truck, 275 ft of 8 inch	CCTV	225061
28	1/19/2015	441 N Luzerne Ave	21224	Trash, Sand, Gravel, Rocks, Other	DWO	N/A	113	Wet paper around clean out	113	Used sewer jet to relieve house connection choke	CCTV	225204
29	1/20/2015	5098 Orville Ave	21205	Pipe Break	DWO	Herring Run	23,421	Gray colored water coming out of pipe	2,342	Repaired crack in pipe that was causing sewage leak	CCTV	225248
30	1/21/2015	217 Southway	21218	Rags, Roots	WWO	N/A	Not Witnessed	Ice and snow around clean out	Evidence of Overflow	Used electric machine to relieve connection choke	CCTV	22633
31	1/21/2015	1232 N Broadway	21213	Rags	WWO	N/A	Not Witnessed	Area wet around clean out	Evidence of Overflow	Used electric machine to relieve choke	CCTV	225977
32	1/21/2015	Cedarcroft Rd & The Alameda	21239	Rags, Trash, Debris, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Gray water around manhole	Evidence of Overflow	Relieved with pressure truck	CCTV	225779
33	1/22/2015	3119 Westmont Ave	21216	Rags, Roots, Grease	WWO	N/A	908	Heavy gray water	9,080	Relieved mainline choke with pressure truck, used 175 ft	CCTV	226408
34	1/24/2015	Beaumont Ave & Northwood Dr	21239	Rags, Grease	WWO	N/A	199	Sewer water around manhole	995	Relieved with pressure jet truck	CCTV	226658
35	1/25/2015	5501 Ritter Ave	21206	Roots	WWO	N/A	Not Witnessed	Toilet paper around clean out	Evidence of Overflow	Ran 45 ft electric machine to relieve choke	CCTV	226717
36	1/25/2015	252 N Hilton St	21229	Rags, Roots, Grease, Trash, Sand, Gravel, Rocks	WWO	Gwynns Falls	933	Gray water, heavy flow	46,650	Relieved mainline choke with pressure truck, 300 ft of 12"	CCTV	226751
37	1/27/2015	422 S Payson St	21223	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	Gwynns Falls	163	Toilet paper & debris	326	Used pressure truck to relieve choke	CCTV	228441
38	1/27/2015	428 E Preston St	21202	Rags	WWO	N/A	Not Witnessed	Tissue and toilet paper around clean out	Evidence of Overflow	Used electric machine to relieve choke	CCTV	228514
39	1/28/2015	526 N Carrollton Ave	21223	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Toilet paper around clean out	Evidence of Overflow	Relieved with 105' of electric machine	CCTV	228565
40	1/28/2015	Greenspring Ave & Loyola Southway	21209	Rags, Roots	DWO	1,665	Jones Falls	Gray water flowing	8,325	Used pressure truck to relieve choke	CCTV Pipe	228570
41	1/29/2015	519 N Streeper St	21205	Trash, Sand, Gravel, Rocks, Pipe Break	DWO	N/A	Not Witnessed	Paper and evidence found around connection	Evidence of Overflow	Relieved choke with electric machine	CCTV	228669
42	1/29/2015	214 Cedarcroft Rd	21212	Roots	DWO	Chinquapin Run	90	Sewage coming out of eyes of manhole cover	180	Cleaned line with pressure truck	Line to Tv'd ASAP	228712
43	1/29/2015	6500 Parnell Ave	21222	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	Colgate Creek	195	Gray colored water and paper	975	Jetted line with pressure truck	Line to be tv'd ASAP	228750
44	1/30/2015	5317 Wendley Rd	21229	Roots	WWO	N/A	Not Witnessed	Toilet paper around clean out	Evidence of Overflow	Relieved house connection choke with electric machine, used 45 ft	CCTV	228891
				# WWO	21			TOTAL	91,015	EVIDENCE ONLY	26	