

## SSO Notification List

July 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/1/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	WWO	Jones Falls	30	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe; not visually observed.	25819	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital project.	
2	7/2/2017	2105 Hollins Ferry Rd	21230	Rags, Roots, Grease	WWO	N/A	0	Water and paper around the cleanout at the rear of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Confirmed connection and mainline are clear.	421290
3	7/2/2017	5115 Norwood Rd	21212	Roots	WWO	N/A	0	Water and paper around the cleanout.	4	Relieved house connection choke with 45 ft of electric cable and auger.	Performed CCTV inspection.	421330
4	7/3/2017	3128 Weaver Ave	21214	Trash	WWO	N/A	0	Water and paper observed around the cleanout at the front of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	421406
5	7/3/2017	3303 Abell Ave	21218	Roots	WWO	N/A	0	Water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	421425
6	7/4/2017	5809 Benton Heights Ave	21206	Rags, Trash	DWO	N/A	0	Water around the cleanout and curb.	16	Relieved house connection choke with 7 ft of electric cable and auger.	Performed CCTV inspection.	421645
7	7/5/2017	6016 Bellona Ave	21212	Rags, Trash	DWO	N/A	0	Grey water in the street.	50	Relieved mainline choke with 220 ft of pressure hose.	Performed mainline CCTV inspection.	421918
8	7/6/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	WWO	Jones Falls	30	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe; not visually observed.	8,877	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
9	7/8/2017	4624 Reisterstown Rd	21215	Trash	WWO	N/A	0	Heavy gray water around the property and sidewalk.	22	Flushed and cleaned 10" mainline with 250 ft of pressure hose.	Performed dye test to check flow.	422474
10	7/11/2017	5306 Valiquet Ave	21206	Rags, Grease	DWO	N/A	0	Gray water around the cleanout at the front of the property.	6	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	423144
11	7/13/2017	3407 Parkside Dr	21206	Roots, Trash	DWO	N/A	0	Water observed around the cleanout.	4	Relieved house connection choke with 30 ft of electric cable and H-Cutter.	Performed house lateral CCTV inspection and cleaned the mainline.	423821
12	7/14/2017	5708 Falls Rd (Private)	21209	Other	DWO	N/A	0	Signs of a overflow between the city and consumer side of the connection coming from out of the ground. This needs to go to housing code enforcement.	10	Notified customer of the issue and contacted Department of Housing for Emergency Sewer Investigation.	N/A	
13	7/14/2017	2801 Annapolis Rd (Private)	21230	Other	DWO	N/A	0	Cloudy water around the private manhole.	1	Customer's information was handed over to Maintenance supervisor. Customer wants to discontinue use of the septic tank and be placed on the City's sewer system.	N/A	423965
14	7/16/2017	3652 Elm Ave	21211	Rags, Roots	DWO	N/A	0	Cloudy gray water and toilet paper were observed around the cleanout.	4	Relieved 6" house connection choke with 60 ft of electric cable and h-cutters.	Performed house lateral CCTV inspection.	424329
15	7/18/2017	337 N Charles St	21202	Rags, Roots, Trash	DWO	N/A	0	Gray water observed around the cleanout.	6	Cleared connection using 60 ft of electric cable.	Performed CCTV inspection and cleaned the mainline.	424933
16	7/20/2017	3600 Keystone Ave	21211	Rags, Grease, Trash, Structural	DWO	Jones Falls	Ongoing	Subsurface overflow found by OCAL during routine monitoring.	Ongoing	Relieved 8" mainline choke with pressure hose. CCTV inspection revealed broken pipe; repair scheduled.	Performed CCTV inspection.	425379
17	7/22/2017	2944 Keswick Rd	21218	Rags, Trash	DWO	N/A	0	Grey water observed around the cleanout at the rear of the property.	0	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	425977
18	7/27/2017	1300 E Northern Pkwy	21239	Rags, Grease, Trash	WWO	N/A	0	Dampness observed around the manhole.	15	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	Performed mainline CCTV inspection.	427263
19	7/28/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	WWO	Jones Falls	15	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	4,693	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	

