

SSO Notification List

June 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/1/2015	714 Glen Allen Dr	21229	Rags, Roots	DWO	N/A	Not Witnessed	Toilet paper and evidence around cleanout	Evidence of Overflow	Relieved house connection choke with 30 ft. of electric machine on 6" pipe	CCTV	257434
2	6/1/2015	306 E 33rd St	21218	Roots, Trash, Sand, Gravel, Rocks	DWO	Jones Falls	34	Heavy paper and roots	170	Cleaned line with electric machine and removed debris	Line to be CCTVd ASAP	257470
3	6/1/2015	5235 Linden Heights Ave	21215	Roots	DWO	N/A	Not Witnessed	Water pressurized from clean out, some evidence of spillage	Evidence of Overflow	Relieved house connection choke with 45ft of electric machine on 6" line	CCTV	257478
4	6/2/2015	1700 Westwood Ave	21217	Rags, Roots	DWO	N/A	Not Witnessed	Toilet paper and murky water around clean out	Evidence of Overflow	Relieved house connection choke with 30 ft of pressure truck on 6" line	CCTV	257588
5	6/2/2015	818 Stamford Rd	21229	Rags, Roots	WWO	N/A	Not Witnessed	Sewer water and toilet paper visible around the clean out	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	257624
6	6/2/2015	1704 W Rogers Ave	21209	Rags, Grease	WWO	N/A	Not Witnessed	Grease and sewer water around manhole	Evidence of Overflow	Used 150 ft of sewer jet to clean line	CCTV	257732
7	6/3/2015	3302 The Alameda	21218	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Wet around clean out, evidence of overflow present	Evidence of Overflow	Used 90 ft. of electric machine and H cutter to remove rags, roots and debris	CCTV	257892
8	6/4/2015	1628 Braddish Ave	21216	Rags, Roots	WWO	N/A	Not Witnessed	Sewer water and toilet paper around the house connection	Evidence of Overflow	Relieved house connection choke with 75 ft of electric machine on 6" line	CCTV	257934
9	6/9/2015	302 S Lehigh St	21224	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	320	Sewer water discharging from consumer sump pump in the rear yard running down the yard in the alleyway due to a mainline choke	1,600	Relieved mainline choke with 450ft of pressure hose	CCTV	258529
10	6/10/2015	2721 Hampden Ave	21211	Rags	WWO	N/A	Not Witnessed	Toilet paper and evidence showing around the clean out	Evidence of Overflow	Left plumbers notice, mainline is clear	CCTV	193936
11	6/10/2015	336 S Calhoun St	21223	Rags, Grease	WWO	N/A	Not Witnessed	Evidence of an overflow around the manhole	Evidence of Overflow	Relieved mainline choke with 200 ft of pressure hose	CCTV	258729
12	6/10/2015	305 Cable St	21210	Rags, Grease	WWO	N/A	Not Witnessed	Evidence of overflow found around clean out	Evidence of Overflow	Used sewer jet to relieve choke	CCTV	258742
13	6/10/2015	1522 E Biddle St	21213	Rags, Grease	WWO	N/A	Not Witnessed	Wet around clean out, evidence of overflow present	Evidence of Overflow	Used 45ft. of electric machine and H-Cutter to relieve choke	CCTV	258701
14	6/10/2015	1910 Eastern Ave	21231	Rags, Grease	WWO	N/A	Not Witnessed	Wet around clean out, evidence of an overflow present	Evidence of Overflow	Used electric machine to remove roots and debris, relieved choke.	CCTV	258695
15	6/10/2015	6100 Boston St	21224	Rags, Grease	WWO	N/A	Not Witnessed	Area is wet around manhole, evidence of an overflow is present	Evidence of Overflow	Used 200 ft of sewer jet to relieve mainline choke	CCTV	258754
16	6/11/2015	220 Presbury St	21216	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Gwynns Falls	176	Heavy sewage flow into storm drain. Confirmed with dye.	3,520	Relieved mainline choke with 210 ft of pressure truck on 8" two section pipe	CCTV	258843
17	6/11/2015	2229 Washington Blvd	21230	Grease	DWO	N/A	266	Heavy gray water flowing from manhole	798	Plumber relieved the choke and flushed the house connection	CCTV	258863
18	6/12/2015	501 S Hanover St	21201	Rags, Roots	DWO	N/A	Not Witnessed	Paper and evidence of an overflow around the house connection	Evidence of Overflow	Relieved house connection choke with 30 ft of electric machine on 6" pipe	CCTV	258977
19	6/12/2015	4304 Sheldon Ave	21206	Other	DWO	N/A	Not Witnessed	Sewer water and evidence around clean out	Evidence of Overflow	Notified consumer of broken house connection on private side	CCTV	259019
20	6/12/2015	2040 Linden Ave	21217	Rags	DWO	N/A	Not Witnessed	Paper and evidence visible around the clean out	Evidence of Overflow	Door notice left for consumer.	Refer Health dept. Turn over clean House Connection close to city mainline.	258991
21	6/15/2015	3300 Clipper Mill Rd	21211	Other	WWO	N/A	Not Witnessed	Evidence only, sewer water infiltrating the system	Evidence of Overflow	Hydraulic analysis was performed to try and help eliminate overflows	Monitor pipe in question	259198

SSO Notification List

June 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	6/16/2015	5916 Frankford Ave	21206	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	Herring Run	120	Heavy paper and sewage flowing from manhole into the stream	1,800	Jetted line and relieved the mainline choke with vac con truck	Line to be CCTVd	259345
23	6/16/2015	2747 Rayner Ave	21216	Rags, Roots	WWO	N/A	Not Witnessed	Rags and evidence found around clean out	Evidence of Overflow	Used electric machine to relieve house connection choke	CCTV	259379
24	6/17/2015	534 Bridgeview Rd	21225	Roots	DWO	N/A	122	Cloudy water coming from front house connection	610	Relieved choke with 30' of electric machine	CCTV	259493
25	6/17/2015	2442 Etting St	21217	Rags	DWO	N/A	Not Witnessed	Gray water and evidence is showing around the clean out	Evidence of Overflow	Relieved the house connection choke with 15' of electric machine	CCTV	259504
26	6/17/2015	5656 The Alameda	21239	Rags, Grease	DWO	N/A	Not Witnessed	Area around clean out is wet, evidence is present	Evidence of Overflow	Used 30' of electric machine to relieve house connection choke	CCTV	259575
27	6/18/2015	1240 N Broadway	21213	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Evidence of overflow around the clean out	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	259639
28	6/20/2015	2601 Boone St	21218	Rags	WWO	N/A	Not Witnessed	Evidence present around the clean out	Evidence of Overflow	Relieved house connection choke with 45ft of electric machine	CCTV	259911
29	6/21/2015	3413 Menlo Dr	21215	Rags, Roots	WWO	N/A	Not Witnessed	Gray Water and evidence showing around the clean out	Evidence of Overflow	Relieved house connection choke with 45ft of electric machine	CCTV	259945
30	6/24/2015	1901 Falls Rd	21217	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray debris	Evidence of Overflow	Cleaned area of debris	Monitor site	260390
31	6/24/2015	4000 The Alameda & Argonne Dr	21218	Rags, Grease	WWO	N/A	Not Witnessed	Wet around manhole	Evidence of Overflow	Used 300 ft of pressure hose to relieve mainline choke	CCTV	260408
32	6/25/2015	2709 Claffin Ct	21225	Trash, Sand, Gravel, Rocks	WWO	N/A	241	Sewer water & toilet paper overflowing from cleanout	2,410	Plumbers notice left on the scene, choke is inside property line on private property	Referred to housing dept.	260499
33	6/26/2015	826 Glenwood Ave	21212	Rags, Roots	DWO	N/A	Not Witnessed	Wet around clean out, sewage evidence present	Evidence of Overflow	Used electric machine to relieve the house connection choke	CCTV	260682
34	6/27/2015	1700 E Chase St	21213	Rain	WWO	Inner Harbor	255	Gray colored water	51,000	Waiting for rain to stop, street has been blocked off	Line to be cleaned with vac con	260756
35	6/28/2015	501 W University Pkwy	21210	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	Jones Falls	1,029	Sewage is overflowing and running into the storm inlet	3,087	Relieved mainline choke with 200' of pressure machine hose	CCTV Mainline	260795
36	6/28/2015	725 Stoney Run Dr	21210	Rags, Grease, Trash, Sand, Gravel, Rocks, Pipe Break	WWO	N/A	Not Witnessed	Evidence of an overflow and sewage present around house connection	Evidence of Overflow	Cleaned line and relieved choke with electric machine	CCTV	260777
37	6/28/2015	2201 Falls Rd	21211	Rain	WWO	Jones Falls	340	Gray colored water and rain water	68,000	Cleaned the mainline with the vector truck	CCTV, monitor during rain events	260801
38	6/28/2015	3321 Spaulding Ave	21215	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Evidence and toilet paper visible around clean out	Evidence of Overflow	Cleaned line with electric machine, relieved house connection choke	Line to be tved	260764
39	6/28/2015	4522 Hamilton Ave	21206	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	Herring Run	57	Heavy sewage and paper flowing from the manhole	1,140	Jetted mainline with vector truck to relieve the mainline choke	This line to be CCTVd ASAP	260789
40	6/29/2015	Falls Rd and Maryland Ave	21211	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Heavy rags, debris and sewage removed from manhole and street	Evidence of Overflow	Removed debris from manhole and street	Monitor during heavy rain events	260865
41	6/30/2015	2905 Woodland Ave	21215	Rags	WWO	N/A	Not Witnessed	Toilet paper and debris visible around the clean out	Evidence of Overflow	Relieved front house connection choke with 45' of Electric Machine	CCTV	261048
42	6/30/2015	2911 Oakley Ave	21215	Rags, Roots	DWO	N/A	Not Witnessed	Rags and evidence around the clean out	Evidence of Overflow	Used 45' of electric machine and H cutter to relieve house connection choke	CCTV	261203
				# WWO	27			TOTAL	134,135	EVIDENCE ONLY	31	