

SSO Notification List

June 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/1/2017	Frankford Estates Dr & Denview Way	21206	Rags, Roots, Grease, Trash	DWO		93	Gray water observed escaping the manhole.	186	Relieved 8" mainline choke with 400 ft of pressure hose.	Performed CCTV inspection.	412042
2	6/1/2017	6001 Bonnie View Dr	21209	Rags, Roots, Trash	DWO		0	Water observed around the cleanout at the front of the property.	4	Relieved 6" house connection choke with 45 ft of electric cable.	Referred for CCTV inspection.	412058
3	6/2/2017	1521 Leslie St	21217	Rags, Roots, Trash	DWO		0	Grey water around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	412450
4	6/5/2017	622 N Pulaski St	21229	Rags	WVO		0	Heavy gray water observed around the cleanout at the rear of the property.	5	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	412742
5	6/5/2017	120 S Monastery Ave	21229	Rags, Grease	WVO		0	Heavy gray water observed around the cleanout at the front of the property.	5	Relieved 6" house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	412614
6	6/8/2017	2546 Marbourne Ave	21230	Rags, Roots	DWO		124	Grey water around the cleanout at the front of the property.	124	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and cleaned the area.	413500
7	6/9/2017	5524 Hilltop Ave	21206	Roots, Trash	DWO		0	Water observed around the cleanout.	4	Relieved house connection choke with 60 ft of electric cable.	Performed house lateral CCTV inspection.	413652
8	6/9/2017	1717 E Fairmount Ave	21231	Roots, Grease, Trash	DWO		44	Gray water around the cleanout and on the sidewalk.	44	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	414015
9	6/10/2017	2257 Cedley St	21230	Grease, Trash	DWO		0	Water and paper observed near the cleanout.	7	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and informed consumer to replace cleanout cap.	414034
10	6/12/2017	1876 Mansion House Dr (Private)	21211	Rags, Roots, Trash	DWO		80	Heavy gray water around the manhole.	1,200	Relieved 8" mainline choke with 150 ft of pressure hose.	Performed mainline CCTV inspection.	414220
11	6/12/2017	1128 W Lafayette Ave	21217	Sand, Gravel, Rocks, Structural	DWO		149	Water flowing from the cleanout in the rear of the property.	149	Relieved house connection choke with 30 ft of electric machine.	Performed CCTV inspection; flushed and cleaned 8" mainline.	416473
12	6/12/2017	5656 The Alameda	21239	Rags, Roots	DWO		0	Grey water and debris around the cleanout on the side of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	416475
13	6/12/2017	1391 Limit Ave	21239	Roots, Trash	DWO		0	Gray water around the cleanout at the front of the property.	6	Relieved house connection choke with 45 ft of electric cable and expander.	Performed house lateral CCTV inspection.	416479
14	6/13/2017	2012 Ramsay St	21223	Rags	DWO		0	Heavy gray water around the cleanout at the rear of the property.	6	Relieved 6" house connection choke with 45 ft of electric cable.	Confirmed house connection and mainline are clear.	416556
15	6/14/2017	428 E Preston St	21202	Rags, Grease, Trash	DWO		0	Water around the cleanout and sidewalk at the front of the property.	6	Relieved house connection choke with pressure hose.	Flushed and cleaned mainline; washed down the area.	416604
16	6/14/2017	115 N Kossuth St	21229	Grease	DWO	Gwynns Falls	126	Subsurface overflow found through routine watershed sampling.	63	Relieved 8" mainline choke with 115 ft of pressure hose.	Performed mainline CCTV inspection.	417035
17	6/14/2017	1706 E 30th St	21218	Rags, Roots, Grease	DWO		0	Water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	417036
18	6/14/2017	534 E Clement St	21230	Roots, Sand, Gravel, Rocks	DWO		0	Gray water around the cleanout at the rear of the property.	8	Unable to relieve choke with 12 ft of electric cable. Referred for bypass pumping.	Confirmed mainline flowing freely.	417278
19	6/14/2017	3118 N Calvert St	21218	Rags, Roots	DWO		0	Gray water with grease and debris around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable and H-cutter.	Performed CCTV inspection.	417270

