

SSO Notification List

March 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	3/3/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	420	Structure monitored by metering equipment in pipe.	2,700,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	667583
2	3/3/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	220	Structure monitored by metering equipment in the pipe. Not visually observed.	350,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	667821
3	3/3/2019	3900 Belair Rd	21206	Rain	Wet	Herring Run	210	Manhole adjacent to creek overflowed due to heavy rain	2,024,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	667883
4	3/5/2019	519 Brisbane Rd	21229	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection.	668241
5	3/5/2019	4309 Springdale Ave	21207	Roots, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout.	4	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	668179
6	3/7/2019	4000 Groveland Ave	21215	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout.	3	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	668427
7	3/7/2019	6303 Pimlico Rd	21209	Rags, Trash	Dry	N/A	81	Choked mainline causing a subsurface SSO to nearby storm drain.	162	Relieved mainline choke with 20 ft of pressure hose.	Performed mainline CCTV inspection.	668564
8	3/8/2019	513 W Mulberry St	21201	Rags, Grease, Trash, Structural	Dry	N/A	0	Gray water observed around the cleanout.	10	Ran 90 ft of electric cable. Investigating possible structural damage in the pipe.	House connection will be repaired. Bypass pumping may be needed to prevent another SSO.	668774
9	3/10/2019	1206 W Northern Pkwy	21209	Roots, Trash	Dry	N/A	0	Gray water and debris observed around the rear cleanout.	10	Relieved 6" house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	669231
10	3/11/2019	4576 Derby Manor Dr	21215	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	7	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	669382
11	3/11/2019	5302 Ethelbert St	21215	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	
12	3/11/2019	1822 N Payson St	21217	Rags, Structural	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Ran 5 ft of electric cable.	Alerted consumer of structural issue on their side of connection.	
13	3/11/2019	2938 Bartol Ave	21209	Rags, Grease, Trash	Wet	N/A	0	Debris observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	671242
14	3/12/2019	1937 E North Ave	21213	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	15	Relieved house connection choke with 3 ft of electric cable.	Performed CCTV inspection; cleaned the mainline.	671350
15	3/13/2019	500 Chateau Ave	21212	Rags, Grease, Trash	Wet	N/A	223	Gray water and debris escaping the manhole in the street.	1,115	Relieved mainline choke with 200 ft of pressure hose.	Performed CCTV inspection.	671532
16	3/14/2019	2304 N Forest Park Ave	21207	Rags, Roots, Grease	Dry	Gwynns Falls	263	Overflowing cleanout in woods. Flowing into street and storm inlet. Found during routine sampling.	263	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; cleaned the mainline.	671713
17	3/14/2019	500 Kane St	21224	Sand, Gravel, Rocks, Structural	Dry	N/A	273	Gray water escaping the manhole.	546	Flushed the mainline; overflow subsided.	Private contractors are involved to return conditions to normal.	671741
18	3/14/2019	1800 Ensor St	21202	Rags, Grease, Trash, Sand, Gravel, Rocks	Dry	N/A	535	Gray water escaping the manhole in the street.	535	Relieved 8" mainline choke with 125 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	671768
19	3/14/2019	436 Kane St	21224	Grease	Dry	N/A	213	Gray water escaping the manhole in the street.	2,130	Relieved mainline choke.	Performed CCTV inspection.	671825
20	3/14/2019	1802 Guilford Ave	21202	Rags, Grease, Trash	Dry	N/A	0	Gray water, paper, and debris observed around the cleanout.	8	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; cleaned the mainline.	671835

SSO Notification List

March 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	3/15/2019	6550 Pioneer Dr	21214	Rags, Roots, Grease	Dry	N/A	153	Gray water escaping the manhole.	306	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	671842
22	3/15/2019	3440 Virginia Ave	21215	Rags, Roots, Grease	Dry	N/A	0	Gray water and debris observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	671851
23	3/15/2019	313 S Augusta Ave	21229	Rags, Roots, Grease	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	10	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; cleaned the mainline.	671866
24	3/18/2019	DuPont Ave & Greenspring Ave	21215	Rags, Roots, Grease	Dry	N/A	0	Gray water observed around the cleanout.	3	Relieved house connection choke with 100 ft of pressure hose.	Confirmed connection is clear.	671881
25	3/19/2019	6303 Pimlico Rd	21209	Structural	Dry	N/A	4,401	Waste water from sanitary line infiltrating storm drain. Found during pollution source tracking.	2,201	Mainline was repaired.	Dye testing confirmed SSO is no longer taking place.	
26	3/19/2019	1711 Guilford Ave	21202	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	672206
27	3/20/2019	2807 Elgin Ave	21216	Rags	Dry	Gwynns Falls	137	Overflowing cleanout in rear of property. Found during pollution source tracking.	69	Relieved house connection choke.	Performed CCTV inspection.	672249
28	3/20/2019	515 E 38th St	21218	Rags, Roots, Grease	Dry	N/A	71	Heavy gray water escaping the cleanout at the rear of the property.	21	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	673149
29	3/21/2019	3310 Ridgewood Ave	21215	Rags, Grease, Trash	Wet	Gwynns Falls	197	Heavy gray water escaping the manhole in the street.	3,940	Relieved mainline choke with 175 ft of pressure hose.	Performed mainline CCTV inspection.	673361
30	3/21/2019	3700 Tudor Arms Ave	21211	Trash, Sand, Gravel, Rocks	Wet	N/A	424	Heavy gray water escaping the manhole.	72,080	Contractor removed blockage in the mainline.	Confirmed mainline is clear.	673543
31	3/21/2019	1731 E Chase St	21213	Rain	Wet	N/A	730	Water escaping manhole in the street.	4,000,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	673538
32	3/21/2019	1901 Falls Rd	21218	Rags, Rain, Infiltration	Wet	Jones Falls	110	Gray water escaping manholes.	818,000	Overflow subsided following heavy rain event.	Locations are equipped with Event Notification System meters.	673604
33	3/21/2019	1600 E Eager St	21205	Rain	Wet	Harbor	730	Gray water escaping the manhole.	6,906,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	673714
34	3/21/2019	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	2,205	Structure monitored by metering equipment in pipe.	18,000,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
35	3/21/2019	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	975	Structure monitored by metering equipment in the pipe. Not visually observed.	6,487,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	674004
36	3/21/2019	N Charles St & W Lanvale St - SSO # 152	21202	Rain	Wet	Jones Falls	70	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	33,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	674092
37	3/21/2019	Charing Cross Rd & GreenWich Ave - SSO #156	21229	Rain	Wet	Maidens Choice	55	Structure monitored by metered equipment in the pipe. Not visually observed.	3,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	674347
38	3/21/2019	E 32nd St & St Paul St- SSO Site #157	21218	Rain	Wet	Jones Falls	45	Structure monitored by metering equipment in pipe	1,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
39	3/21/2019	3900 Belair Rd	21206	Rain	Wet	Herring Run	605	Manhole adjacent to creek overflowed due to heavy rain.	8,788,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	674495
40	3/24/2019	2131 W Mulberry St	21223	Rags, Grease	Wet	N/A	0	Gray water observed around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	
41	3/25/2019	1200 N Franklinton Rd	21216	Rags, Grease, Trash	Wet	Gwynns Falls	175	Heavy gray water escaping the manhole.	1,750	Relieved 8" mainline choke with 60 ft of pressure hose.	Confirmed mainline is clear.	

SSO Notification List

March 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
42	3/26/2019	17 W Barre St	21201	Rags, Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	
43	3/26/2019	1613 Gwynns Falls Pkwy	21217	Rags, Grease, Trash	Dry	N/A	136	Gray water escaping the manhole in the alley.	272	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	
44	3/26/2019	1214 Homewood Ave	21202	Rags, Roots, Trash	Dry	N/A	155	Gray water escaping the cleanout at the rear of the property.	310	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	
45	3/27/2019	N Franklinton Rd & W Fairmount Ave	21223	Rags, Grease, Trash	Dry	Gwynns Falls	71	Sanitary mainline choke causing subsurface overflow into storm drain.	213	Relieved mainline choke with 400 ft of pressure hose.	Performed CCTV inspection.	
46	3/27/2019	6303 Pimlico Rd	21209	Structural	Dry	N/A	2,902	Structural damage to pipe causing subsurface overflow.	5,804	Performed an open cut repair to the mainline.	Confirmed abatement via dye testing.	
47	3/27/2019	16 Elmwood Rd	21210	Roots, Structural	Dry	Jones Falls	Ongoing	Broken sewer pipe overflowing into adjacent storm pipe.	Ongoing	Line will be repaired.	Bypass pumping may be set up to stop the overflow.	
48	3/27/2019	5007 Midwood Ave	21212	Trash, Sand, Gravel, Rocks	Dry	N/A	0	Heavy gray water observed around the cleanout.	3	Ran 6 ft of electric cable and removed obstructions.	Bypass pumping may be needed while further investigation occurs.	
49	3/28/2019	1105 Argonne Dr	21218	Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with electric cable.	Performed CCTV inspection.	
50	3/29/2019	2300 Garrison Blvd	21216	Rags, Roots	Dry	N/A	38	Water escaping the manhole in the street.	19	Relieved mainline choke with 200 ft of pressure hose.	Performed CCTV inspection.	
51	3/29/2019	Greenspring Ave & DuPont Ave	21209	Rags, Trash	Dry	Jones Falls	89	Gray water and debris exiting below cleanout.	22	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lines are clear.	
52	3/30/2019	3836 Bank St	21224	Rags, Grease, Trash	Dry	N/A	126	Heavy gray water running in the rear alley.	252	Relieved mainline choke with 300 ft of pressure hose.	Performed CCTV inspection.	
53	3/30/2019	2219 E Lombard St	21231	Rags, Trash, Sand, Gravel, Rocks	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed the mainline.	
				# WWO	25			TOTAL	50,202,125	UNDER 100 GALLONS	24	