

## SSO Notification List

May 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/1/2017	5224 York Rd	21209	Rags, Roots	DWO		0	Gray water around the cleanout at the front of the property.	2	Relieved house connection choke with 60 ft of electric cable.	Performed house lateral CCTV inspection.	404835
2	5/1/2017	4907 Frankford Ave	21206	Rags, Trash	WWO		0	Gray water around the cleanout at the front of the property.	4	Relieved house connection choke with 45 ft of electric cable and H-cutter.	Performed house lateral CCTV inspection.	405069
3	5/1/2017	5921 Moravia Park Dr (Private)	21206	Structural	DWO	Herring Run	0	Heavy gray water around private house connection.	10	Location was turned over to HCD.	Informed resident that the problem is on their side.	404970
4	5/1/2017	2001 E 30th St	21218	Rags, Roots	WWO		124	Gray water coming from the cleanout at the rear of the property.	124	Relieved house connection with 75 ft of electric cable and H-cutter.	Left a door notice to inform consumer.	405081
5	5/3/2017	601 W Patapsco Ave (Private)	21225	Rags, Trash	DWO		112	Heavy gray water overflowing from manhole.	2,800	Flushed and cleaned 21" mainline.	Turned the bypass pumps up to stop the overflow.	405512
6	5/3/2017	1800 Washington Blvd (Private)	21230	Rags, Trash	DWO		0	Heavy gray water observed around cleanout.	10	Relieved 2" house connection choke with 250 ft of pressure hose.	Flushed 6" mainline.	405545
7	5/4/2017	4108 Hayward Ave	21215	Rags, Grease	DWO		0	Grey water observed around the cleanout.	12	Relieved house connection with 8 ft of electric cable. Relieved 8" mainline choke with 200 ft of pressure hose.	Performed a lateral CCTV inspection and flushed mainline.	405819
8	5/5/2017	1814 N Bond St	21213	Rags, Trash	WWO		0	Gray water around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cables.	Performed house lateral CCTV inspection.	405962
9	5/5/2017	1901 Falls Road - SSO #67	21217	Rain	WWO	Jones Falls	165	Structure monitored by metering equipment in the pipe.	450,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
10	5/5/2017	428 E Preston St - SSO #72	21202	Rain	WWO	Jones Falls	205	Structure monitored by metering equipment in the pipe. Not visually observed.	2,618,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
11	5/5/2017	W Garrison Ave & Queensberry Rd - SSO #139	21215	Rain	WWO	Jones Falls	80	Structure monitored by metering equipment in the pipe; not visually observed.	32,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
12	5/5/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	WWO	Jones Falls	205	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	63,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
13	5/6/2017	1400 N Dukeland St	21216	Rags, Grease, Trash	WWO		129	Heavy gray water.	258	Flushed and cleaned 8" mainline.	Performed mainline CCTV inspection.	406125
14	5/6/2017	4201 Kenshaw Ave	21215	Rags, Roots	WWO		0	Heavy gray water around the cleanout at the front of the property.	6	Relieved 6" house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	406149
15	5/6/2017	5502 Benton Heights Ave	21206	Rags, Roots	WWO		0	Heavy gray water around the cleanout at the front of the property.	2	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	406196
16	5/7/2017	215 Beale Ct	21231	Rags, Grease	WWO		0	Heavy gray water around the cleanout.	15	Relieved house connection choke with 300 ft of pressure hose.	Performed house lateral CCTV inspection.	406254
17	5/8/2017	413 Wingate Rd	21210	Roots, Grease, Trash	WWO		84	Flowing gray water observed around manhole.	84	Relieved 8" mainline with 400 feet of pressure hose.	Performed mainline CCTV inspection.	406478
18	5/8/2017	633 Roland Spring Dr	21212	Roots, Grease	WWO		170	Flowing gray water observed around manhole.	170	Relieved 8" mainline choke with 200 feet of pressure hose.	Performed mainline CCTV inspection.	406444
19	5/9/2017	638 Oldham St	21224	Roots, Sand, Gravel, Rocks	DWO		0	Minimal gray water observed around cleanout.	5	Relieved house connection choke with 30 feet of electric cable and h-cutter.	Cleaned surrounding area.	406786

## SSO Notification List

May 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	5/9/2017	4532 Harford Rd	21214	Rags, Roots	DWO		0	Gray water observed around cleanout.	5	Relieved house connection choke with 45 feet of electric cable and H-cutter.	Mainline cleaning scheduled.	406808
21	5/9/2017	4110 Hayward Ave	21215	Rags, Trash	WVO		0	Gray water observed on the sidewalk near the cleanout.	8	Relieved house connection choke with 30 ft of electric cable and H-cutter.	Washed down the area.	406821
22	5/10/2017	2219 E Lombard St	21231	Rags, Trash	DWO		0	Water around the cleanout at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable and H-cutter.	Performed house lateral CCTV inspection. Flushed and cleaned the mainline.	407081
23	5/10/2017	3105 Puget St	21230	Rags, Roots	DWO		0	Heavy gray water around the manhole and cleanout at location.	33	Relieved 8" mainline choke with 100 ft of pressure hose. Replaced cap on cleanout.	Referred for mainline CCTV inspection.	406995
24	5/13/2017	4613 Briarclift Rd	21229	Rags, Structural	WVO		203	Heavy gray water coming from the manhole.	5,075	Relieved 12" mainline choke with 350 ft of pressure hose.	Performed CCTV inspection; flushed and cleaned the mainline.	407644
25	5/15/2017	1612 Aisquith St	21202	Rags, Grease	DWO	Jones Falls	0	Grey water reaching basement of property.	1,225	Flushed and cleaned 8" mainline using 200 ft of pressure hose.	Performed mainline CCTV inspection.	405716
26	5/16/2017	2801 Presbury St	21216	Rags, Grease, Trash	WVO		0	Water observed around the manhole.	9	Relieved 8" mainline choke with 50 ft of pressure hose.	Performed mainline CCTV inspection.	407990
27	5/16/2017	Wilkens Ave & Hurley Ave	21223	Rags, Trash, Sand, Gravel, Rocks	WVO	Gwynns Falls	238	Water overflowing from a manhole inside of a park.	4,760	Relieved 8" mainline choke with 20 ft of pressure hose.	Performed mainline CCTV inspection. Flushed and cleaned the mainline.	408213
28	5/18/2017	1908 Ramblewood Rd	21239	Rags, Grease, Trash	DWO	Herring Run	186	Gray water flowing from the cleanout.	186	Relieved house connection choke with 60 ft of electric cable and H-cutter.	Performed CCTV inspection; flushed and cleaned the mainline.	408849
29	5/19/2017	N Charles St & W Lanvale St - SSO #152	21201	Rain	WVO	Jones Falls	15	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	21	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
30	5/20/2017	421 E 22nd St	21218	Rags, Grease	WVO		0	Water observed around the cleanout at the rear of the property.	9	Relieved 6" house connection choke with 60 ft of electric cable.	Performed house lateral CCTV inspection.	409277
31	5/20/2017	1631 Gwynns Falls Pkwy	21217	Rags, Roots	WVO		0	Heavy gray water around the cleanout at the rear of the property.	4	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	409339
32	5/21/2017	1908 Ramblewood Rd (Private)	21239	Rags, Grease, Other	WVO		0	Grey water around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and contacted customer.	409438
33	5/22/2017	1010 Whistler Ave	21223	Rags, Roots	WVO		0	Heavy gray water observed around the cleanout.	9	Relieved 6" house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection and confirmed connection is flowing freely.	409480
34	5/22/2017	809 N Caroline St	21205	Roots, Grease, Trash	WVO		0	Water observed around the cleanout.	4	Relieved house connection choke with 30 ft of electric cable and H-cutter.	Performed house lateral CCTV inspection; flushed and cleaned the 8" mainline.	409665
35	5/22/2017	1207 Springfield Ave	21239	Trash	WVO		91	Water overflowing from manhole.	455	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	409501
36	5/23/2017	1823 McCulloh St	21217	Structural, Unknown	WVO		0	Grey water around the cleanout at the rear of the property.	12	Unable to relieve house connection choke with pressure hose or electric cable. Established bypass pump to stop overflow; referred pipe for repair.	Performed CCTV inspection.	410090
37	5/24/2017	2801 N Dukeland St (Private)	21216	Rags, Trash	WVO		186	Gray water observed coming from the manhole.	558	Relieved 4" mainline choke with 175 ft of pressure hose.	Performed mainline CCTV inspection.	410274
38	5/24/2017	5700 Belair Rd	21206	Rags, Trash	WVO		0	Grey water observed around the cleanout.	4	Relieved house connection choke with 60 ft of electric cable and H-cutter.	Performed house lateral CCTV inspection; flushed and cleaned 8" mainline.	410390
39	5/25/2017	N Charles St & W Lanvale St - SSO#152	21201	Rain	WVO	Jones Falls	20	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	2,550	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	

