

SSO Notification List

November 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/1/2017	2518 Talbot Rd	21216	Trash, Sand, Gravel, Rocks	WWO	N/A	120	Water flowing out of the manhole in the street.	120	Relieved 8" mainline choke with 100 ft of pressure hose.	Performed mainline CCTV inspection.	463327
2	11/3/2017	1425 Aliceanna St	21231	Rags, Grease	DWO	N/A	80	Heavy gray water escaping the manhole.	240	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	464646
3	11/7/2017	3708 Frankford Ave	21206	Rags, Roots, Trash	WWO	N/A	0	Gray water around the manhole and surrounding area.	500	Relieved mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	465414
4	11/9/2017	5300 Plymouth Rd	21214	Grease, Trash, Sand, Gravel, Rocks	WWO	Herring Run	76	Subsurface overflow located by OCAL during routine sampling.	8	Flushed and cleaned 8" mainline with 150 ft of pressure hose.	Performed mainline CCTV inspection.	466007
5	11/10/2017	710 N Fulton Ave	21217	Rags, Trash	WWO	N/A	0	Water observed around the cleanout.	4	Relieved house connection choke with 45 ft of electric cable and flushed house connection with pressure hose.	Performed CCTV inspection; cleaned 8" mainline.	466270
6	11/10/2017	1412 N Luzerne Ave	21213	Grease	WWO	N/A	0	Heavy gray water observed around the cleanout.	5	Relieved 6" house connection choke with 60 ft of electric cable.	Performed house lateral CCTV inspection; flushed and cleaned the mainline.	466294
7	11/11/2017	4907 Frankford Ave	21206	Rags, Grease	DWO	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and cleaned the 8" mainline.	466358
8	11/12/2017	429 Swale Ave	21225	Rags, Grease, Trash	DWO	N/A	221	Gray water coming from consumer's sump pumps caused by choked mainline.	884	Relieved 10" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	466367
9	11/12/2017	1700 S Caton Ave	21227	Rags, Roots	DWO	N/A	0	Heavy gray water around the cleanout at the rear of the property.	5	Relieved 6" house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	466377
10	11/13/2017	2608 Washington Blvd	21230	Rags, Roots	DWO	N/A	0	Dampness observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	466697
11	11/14/2017	2231 Crest Rd	21209	Structural	DWO	N/A	10295	Sanitary sewer lateral leaking into storm drain inlet pipe. Discovered during routine sampling.	515	City maintenance crew repaired structural damage to the pipe.	Office of Compliance and Laboratories confirmed abatement via dye testing.	467053
12	11/15/2017	428 E Preston St	21202	Trash	DWO	N/A	0	Gray water and debris observed on the street and sidewalk.	60	Relieved mainline choke with 60 ft of pressure hose.	Performed CCTV inspection.	467760
13	11/18/2017	3035 Gwynns Falls Pkwy	21216	Trash	DWO	N/A	0	Gray water observed around the sidewalk and street.	10	Relieved 8" mainline choke with 500 ft of pressure hose.	Performed mainline CCTV inspection.	468591
14	11/18/2017	6541 Eastern Ave	21224	Rags, Grease	DWO	N/A	0	Water escaping from manhole in parking lot.	80	Relieved mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	468620
15	11/18/2017	4008 Hamilton Ave	21206	Rags, Grease	DWO	N/A	0	Gray water observed around the cleanout on front lawn.	5	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	468636
16	11/18/2017	220 S Payson St	21223	Trash	DWO	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 15 ft of electric cable.	Performed house lateral CCTV inspection.	468592
17	11/20/2017	1600 S Monroe St	21230	Rags, Grease	DWO	N/A	296	Heavy gray water escaping the manhole on the side of the property.	888	Relieved mainline choke with 230 ft of pressure hose.	Performed mainline CCTV inspection.	468778
18	11/21/2017	4719 Midwood Ave	21212	Trash	DWO	N/A	0	Gray water around the cleanout at the front of the property.	8	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	470423
19	11/21/2017	3800 Labyrinth Rd	21215	Rags	DWO	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	8	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	470566

SSO Notification List

November 2017

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	11/21/2017	3128 Harview Ave	21234	Rags, Grease, Trash	DWO	N/A	40	Heavy water discharging from consumer's sump pump.	40	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	Confirmed mainline is clear.	470821
21	11/21/2017	613 N Carney St	21217	Rags, Roots, Trash	DWO	N/A	0	Gray water observed around the cleanout at the rear of the property.	8	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	470792
22	11/22/2017	836 E Preston St	21202	Rags, Roots, Trash	DWO	N/A	26	Water overflowing from cleanout at the rear of the property.	26	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	471424
23	11/25/2017	3005 Clearview Ave	21234	Rags, Trash	DWO	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	2	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the 8" mainline.	471772
24	11/26/2017	3600 Clarks Ln	21215	Rags, Grease, Trash	DWO	N/A	50	Water escaping manhole in the alley.	100	Relieved 8" mainline choke with 20 ft of pressure hose.	Performed mainline CCTV inspection.	471802
25	11/26/2017	5000 Wilmslow Rd	21210	Rags, Grease	DWO	N/A	73	Water escaping a manhole.	73	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	471814
26	11/27/2017	1915 E 30th St	21218	Rags	DWO	N/A	0	Grey water observed around the cleanout and alley at the rear of the property.	11	Relieved house connection choke with 30 ft of electric cable.	Performed house lateral CCTV inspection.	471976
27	11/28/2017	1120 Gorsuch Ave	21218	Rags, Roots, Trash	DWO	N/A	0	Water observed around the cleanout at the front of the property.	6	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	472467
28	11/28/2017	904 Bennett Pl	21201	Trash, Sand, Gravel, Rocks	DWO	N/A	406	Gray water flowing from the cleanout at the rear of the property.	812	Relieved choke with 30 ft of electric cable and auger.	Performed CCTV inspection; flushed and cleaned 8" mainline.	472657
29	11/29/2017	1022 E 20th St	21218	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	131	Gray water flowing from the cleanout.	131	Relieved house connection choke with 13 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	473088
				# WWO	5			TOTAL	4,559	UNDER 100 GALLONS	20	