

SSO Notification List

NOVEMBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/2/2018	Dupont Ave & Greenspring Ave	21209	Rags, Roots, Grease, Trash	Wet	Jones Falls	100	Sewage escaping cleanout at the front of the property.	500	Relieved 6" house connection choke with 35 ft of pressure hose.	Confirmed connection is clear.	633175
2	11/2/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	15	Structure monitored by metering equipment in pipe.	125	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
3	11/2/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	200	Structure monitored by metering equipment in pipe.	917,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
4	11/3/2018	4309 Liberty Heights Ave	21207	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout.	8	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection; flushed and cleaned 8" mainline.	633435
5	11/3/2018	526 N Highland Ave	21205	Rags, Roots	Wet	N/A	0	Water observed around the cleanout at the front of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	633459
6	11/4/2018	6434 O'Donnell St - Private	21224	Rags, Grease, Trash	Wet	N/A	141	Heavy gray water escaping privately-owned manhole.	2,820	Relieved 8" mainline choke with 30 ft of pressure hose.	Performed mainline CCTV inspection.	633588
7	11/5/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	100	Structure monitored by metering equipment in pipe.	29,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
8	11/5/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	400	Structure monitored by metering equipment in pipe.	2,258,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
9	11/6/2018	1901 Falls Rd	21201	Rain	Wet	N/A	25	Manhole surcharging due to heavy rain event.	2,000	Overflow subsided following heavy rain event.	Location is monitored by an Event Notification System.	634050
10	11/6/2018	4516 Furley Ave	21206	Rags, Roots, Trash	Wet	N/A	107	Gray water escaping the cleanout at the side of the property.	107	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	634079
11	11/6/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	565	Structure monitored by metering equipment in pipe.	5,199,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
12	11/6/2018	1731 E Chase St	21213	Rain	Wet	N/A	55	Water escaping manhole in the street.	46,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
13	11/6/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	275	Structure monitored by metering equipment in pipe.	456,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
14	11/6/2018	1800 E Eager St	21205	Rain	Wet	N/A	20	Water surcharging from manhole due to heavy rain event.	287,000	Flow returned to normal following heavy rain event.	Location is equipped with an Event Notification System meter.	634028
15	11/6/2018	1701 E Patapsco Ave	21226	Other	Wet	N/A	15	Sewage spilled from bypass pump after removing plug.	50	Redirected flow toward storm drain and replaced plug.	Reinforced protocols with contractor.	
16	11/7/2018	3909 Chatham Rd	21207	Rags, Trash	Wet	N/A	114	Gray water escaping a sump pump.	228	Flushed and cleaned 8" mainline with 500 ft of pressure hose.	Advised resident to contact a plumber for private-side issue.	634729
17	11/7/2018	1250 Gay St	21213	Rags, Grease, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; cleaned mainline.	634590
18	11/10/2018	3100 Edmondson Ave	21216	Trash, Sand, Gravel, Rocks	Wet	N/A	2,500	Grey water escaping manhole.	5,000	Ran 15 ft of pressure hose to flush the mainline.	Private contractors working on-site will monitor the area to ensure flow returned to normal.	636331
19	11/12/2018	2716 Saint Paul St	21218	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 60 ft of electric cable.	Confirmed mainline and lateral are clear.	640459
20	11/12/2018	839 Ramsey St	21230	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	640462

SSO Notification List

NOVEMBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	11/12/2018	6434 O'Donnell St	21224	Rags, Grease, Trash	Wet	N/A	962	Gray water escaping the manhole.	1,924	Relieved 8" mainline choke with 70 ft of pressure hose.	Confirmed mainline is clear.	640469
22	11/13/2018	517 N Pulaski St	21223	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed house lateral CCTV inspection.	640858
23	11/13/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	375	Structure monitored by metering equipment in pipe.	554,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
24	11/13/2018	2036 Druid Hill Ave	21217	Rags, Roots	Wet	N/A	1,229	Heavy gray water escaping the cleanout at the rear of the property.	1,229	Relieved 6" house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	640868
25	11/14/2018	2029 E Baltimore St	21231	Grease, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	20	Relieved house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	641124
26	11/14/2018	3627 4th St	21225	Roots, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	5	Ran 45 ft of electric cable.	Performed CCTV inspection; advised consumer to check private side.	641163
27	11/15/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	1,300	Structure monitored by metering equipment in pipe.	7,114,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
28	11/15/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	655	Structure monitored by metering equipment in pipe.	2,032,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
29	11/16/2018	Kirk Ave & Exeter Hall Ave	21218	Structural	Wet	N/A	10	Heavy gray water escaping onto the street.	500	Cleaned the area and alerted pump station staff about issue.	Investigating nearby force main, gravity sewer, and storm drain.	641989
30	11/20/2018	2115 Lyndhurst Ave	21216	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved 6" house connection choke with 90 ft of electric cable.	Performed CCTV inspection; cleaned mainline.	642694
31	11/20/2018	2029 E Baltimore St	21231	Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	15	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	642801
32	11/21/2018	1600 W 41st St	21211	Rags, Roots, Trash, Sand, Gravel, Rocks	Dry	N/A	152	Heavy gray water escaping the manhole.	2,280	Relieved 8" mainline choke with 115 ft of pressure hose.	Performed mainline CCTV inspection.	642887
33	11/21/2018	Ravenwood Ave & Longview Ave	21213	Rags, Grease	Dry	Herring Run	98	Sanitary mainline choke causing wastewater to infiltrate storm drain.	490	Relieved 8" mainline choke with 200 ft of pressure hose.	Performed mainline CCTV inspection.	643224
34	11/21/2018	4812 Sipple Ave	21206	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	643299
35	11/21/2018	4307 N Charles St	21218	Rags, Roots	Dry	N/A	0	Heavy gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	643306
36	11/22/2018	1100 Edwight Ct	21225	Rags, Roots, Grease, Trash	Dry	N/A	1,120	Gray water escaping the manhole.	2,240	Relieved 8" mainline choke with 5 ft of pressure hose.	Confirmed mainline is clear.	643338
37	11/24/2018	1901 Falls Rd	21218	Rags, Rain	Wet	Jones Falls	185	Water escaping multiple manholes in the street.	90,500	Overflows subsided following heavy rain event.	Locations are equipped with Event Notification System meters.	
38	11/24/2018	3712 Windsor Mill Rd	21216	Rags, Grease, Trash	Wet	Gwynns Falls	42	Gray water escaping the manhole in the street.	1,050	Relieved 8" mainline choke with 20 ft of pressure hose.	Performed mainline CCTV inspection.	643705
39	11/24/2018	1800 E Eager St	21205	Rags, Rain, Trash	Wet	N/A	140	Water escaping manhole in the street.	444,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	643704
40	11/24/2018	1731 E Chase St	21213	Rain, Trash	Wet	N/A	215	Water escaping manhole in the street.	2,504,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	643702
41	11/24/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	525	Structure monitored by metering equipment in pipe.	6,753,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	

SSO Notification List

NOVEMBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
42	11/24/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	405	Structure monitored by metering equipment in pipe.	2,298,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
43	11/24/2018	3900 Belair Rd	21206	Rain	Wet	Herring Run	250	Manhole adjacent to creek overflowed due to heavy rain storm.	1,831,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	
44	11/25/2018	3128 Northway Dr	21234	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection.	643782
45	11/27/2018	2220 Madison Ave	21217	Grease, Trash	Wet	N/A	0	Gray water observed around the manhole.	10	Relieved mainline choke with 100 ft of pressure hose.	CCTV inspection; further investigation for potential water leak.	644369
46	11/30/2018	320 W 29th St	21211	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout.	15	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection; left notice to install cleanout cap.	644977
				# WWO	38			TOTAL	32,830,227	UNDER 100 GALLONS	17	