

SSO Notification List

September 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	9/2/2015	3500 Cottage Ave	21215	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	300	Sewage overflowing from manhole in middle of street	3,000	Relieved mainline choke with 285 ft of pressure truck on 8" sanitary line	CCTV	269435
2	9/2/2015	Saint Paul Pl & Saratoga St	21202	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Inner Harbor	863	Sewage was running from manhole, caused by mainline choke	4,315	Jetted line with vactor truck, bypass pumping is needed to abate overflow	CCTV	269438
3	9/3/2015	2229 Washington Blvd	21230	Grease	DWO	N/A	Not Witnessed	Grease and water around manhole	Evidence of Overflow	Used 300' of sewer jet to relieve mainline choke on 8" line	CCTV	269712
4	9/6/2015	700 Pennsylvania Ave	21201	Rags, Grease, Unknown	DWO	N/A	94	Paper	376	Relieved the mainline choke with 300' of Pressure Hose.	C.C.T.V. Mainline	269969
5	9/6/2015	3714 Elkader Rd	21218	Roots	DWO	N/A	Not Witnessed	Gray Water, evidence of spillage around the clean out	Evidence of Overflow	Relieved house connection choke with 30' of Electric Machine	C.C.T.V.	269974
6	9/7/2015	1822 E North Ave	21213	Rags, Roots	DWO	N/A	Not Witnessed	Signs of overflow around the clean out	Evidence of Overflow	Relieved house connection choke with 15 ft of electric machine on 6" pipe	CCTV	269999
7	9/9/2015	1740 E Lanvale St	21213	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Sewage, paper and evidence visible around the clean out in the rear of the building	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV, temporarily relieved	270296
8	9/9/2015	5028 Queensberry Ave	21215	Rags	DWO	N/A	Not Witnessed	Wet paper around clean out in the front of the building	Evidence of Overflow	Used 30' of electric machine to relieve house connection choke	CCTV	270348
9	9/10/2015	3500 Cottage Ave	21215	Rags, Grease	WWO	N/A	Not Witnessed	Wet around manhole	Evidence of Overflow	Relieved mainline choke with 200 ft of sewer jet, removed roots and debris	CCTV	270553
10	9/11/2015	6410 Loch Raven Blvd	21239	Rags, Roots	WWO	N/A	Not Witnessed	Wet around clean out, evidence present	Evidence of Overflow	Used 90' of electric machine to relieve house connection choke	CCTV	270852
11	9/12/2015	Edmondson Ave and N Hilton St	21229	Grease	WWO	N/A	120	Grease and sewage coming from manhole	1,800	Relieved with pressure truck	CCTV	270925
12	9/13/2015	109 N Central Ave	21231	Grease	WWO	Inner Harbor	54	Found mainline choke, active overflow running from Manhole.	540	Relieved 8" line with 100' with pressure truck	CCTV	271030
13	9/15/2015	3900 Harford Rd	21206	Grease	DWO	Herring Run	Not Witnessed	OCAL staff was notified by contractors that large overflow occurs during rain events.	Evidence of Overflow	Overflow relieved itself by the time DPW arrived on scene	CCTV	271436
14	9/16/2015	1809 W Lexington St	21223	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	336	Rear house connection choke, active overflow from cleanout	1,680	Relieved house connection choke with 45 ft of pressure hose and mainline choke with 250 ft of pressure hose.	CCTV	271603
15	9/16/2015	5113 Falls Rd	21210	Pipe Break	DWO	Jones Falls	1,385	Sewage overflowing into storm drain At this location. Verified by dye testing. OCAL	346	CCTV mainline and stormline, found offset joints with cracks in pipe. Turned over to construction for repair	SSO is ongoing, pipe will be repaired.	271658
16	9/16/2015	Edmondson Ave and N Hilton St	21229	Rags, Roots, Grease	DWO	Gwynns Falls	143	Overflowing sanitary manhole under Edmondson bridge	7,150	Relieved mainline choke with 250 ft of pressure truck on 10" line	CCTV	271645

SSO Notification List

September 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
17	9/17/2015	2401 Crest Rd	21209	Rags, Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	1,092	Mainline choke causing overflow	2,184	Relieved mainline choke with 50 ft of pressure truck on 8"	CCTV	272868
18	9/18/2015	816 S Decker St	21224	Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Paper and evidence around the clean out	Evidence of Overflow	Cleaned line with electric machine, relieved house connection choke	Line to be tved	272911
19	9/18/2015	1333 N Milton Ave	21213	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Northwest Harbor	107	OCAL detected wastewater in a storm drain leaving a choked sanitary line	535	Jetted line with 250ft of pressure hose, relieved mainline choke	Line to be tved	272954
20	9/18/2015	1814 N Calvert St	21202	Rags, Grease	DWO	N/A	Not Witnessed	Paper and evidence visible around the clean out.	Evidence of Overflow	Used 60ft of electric machine to relieve house connection choke	CCTV	272966
21	9/19/2015	1951 Edmondson Ave	21223	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Paper and evidence visible	Evidence of Overflow	Cleaned line with 45ft of electric machine, removed rags and roots	Line to be tved	273027
22	9/19/2015	4508 Bonner Rd	21216	Grease	DWO	N/A	Not Witnessed	Wet around manhole, evidence present	Evidence of Overflow	Used 400ft of sewer jet to relieve mainline choke	CCTV	273046
23	9/19/2015	Morris Rd and N Franklinton Rd	21216	Rags, Roots, Grease	DWO	Gwynns Falls	357	Mainline choke causing sewage to overflow from manhole	1,071	Used 400ft of pressure hose, removed rags and roots to relieve mainline choke.	CCTV	273030
24	9/19/2015	2500 Queen Anne Rd	21216	Rags, Grease	DWO	N/A	1,291	Sewage overflowing from the manhole	2,582	Relieved mainline choke with 150ft of pressure hose	CCTV	273050
25	9/20/2015	410 E 31st St	21218	Roots	DWO	N/A	Not Witnessed	Rear house connection choke evidence of an overflow	Evidence of Overflow	Cleaned line with 30ft of electric machine	Line to be tved	273078
26	9/21/2015	6803 Hamlet Ave	21234	Roots	DWO	N/A	Not Witnessed	Paper and evidence visible around the clean out	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	273123
27	9/21/2015	3500 Cottage Ave	21215	Rags, Grease	DWO	N/A	Not Witnessed	Wet around manhole, evidence is present.	Evidence of Overflow	Relieved mainline choke with 45ft of sewer jet.	CCTV	273207
28	9/22/2015	1000 Ellicott Dr	21229	Pipe Break	DWO	Gwynns Falls	1,623	Heavy gray water leaking from sanitary mainline	3,246	Construction repaired a 10" inch sanitary pipe leaking into the stream	Repair made with clamps to stop leak	273340
29	9/23/2015	202 Longwood Rd	21210	Roots, Trash, Sand, Gravel, Rocks	DWO	N/A	Not Witnessed	Gray Water and evidence visible around the house connection.	Evidence of Overflow	Relieved house connection choke with 80' of Pressure Machine Hose	CCTV	273465
30	9/23/2015	1032 Parksley Ave	21223	Rags, Roots	DWO	N/A	Not Witnessed	Wet on ground curb	Evidence of Overflow	Used elec mach	CCTV	273571
31	9/23/2015	147 N Streeper St	21224	Grease	DWO	N/A	Not Witnessed	Rear house connection choke evidence of an overflow	Evidence of Overflow	Used elec mach	CCTV	273537
32	9/23/2015	830 N Broadway St	21205	Trash, Sand, Gravel, Rocks, Pipe Break	DWO	N/A	Not Witnessed	Rear house connection chock evidence of an overflow	Evidence of Overflow	Relieved with electric machine	T/O to repair broken pipe	273539

