

## SSO Notification List

SEPTEMBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	9/4/2018	504 Edgevale Rd	21210	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	613525
2	9/4/2018	1400 Elmtree St	21226	Rags, Roots, Grease	Dry	N/A	267	Gray water and debris escaping cleanout.	267	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	613784
3	9/4/2018	6803 Hamlet Ave	21234	Roots	Dry	N/A	0	Gray water and debris observed around the cleanout.	3	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed connection and mainline are clear.	613791
4	9/5/2018	1200 N Franklinton Rd	21216	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the manhole.	3	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	613953
5	9/5/2018	2570 Marbourne Ave	21230	Rags, Roots	Dry	N/A	297	Gray water escaping cleanout at the front of the property.	149	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	614028
6	9/5/2018	2803 Goodwood Rd	21214	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	614032
7	9/6/2018	1111 Dundalk Ave	21224	Rags, Trash	Dry	N/A	0	Water observed around the manhole on the sidewalk.	5	Flushed and cleaned 8" mainline with 400 ft of pressure hose.	Performed mainline CCTV inspection.	614226
8	9/6/2018	4138 Norfolk Ave	21216	Structural	Dry	N/A	0	BGE struck a lateral while making an installation, causing sewage to be released.	10	Point repair scheduled for house connection.	Performed CCTV inspection.	614305
9	9/7/2018	4800 Falls Rd	21210	Rags, Roots, Grease, Trash	Dry	N/A	272	Heavy gray water escaping the manhole.	4,080	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection.	614405
10	9/7/2018	Western Run Dr & Bonnie View Dr	21209	Rain	Wet	N/A	0	Water surcharging from stacked manhole.	30,000	Conditions returned to normal following heavy rain event.	This stacked manhole is susceptible to overflow when reaching capacity. City is aware of repeated overflows at this location.	
11	9/9/2018	1901 Falls Rd	21218	Rain	Wet	Jones Falls	820	Manhole surcharging due to heavy rain event.	82,000	Overflow subsided following heavy rain event.	Location is monitored by an Event Notification System.	614717
12	9/9/2018	3712 Windsor Mill Rd	21216	Rain	Wet	N/A	0	Water escaped out of manhole in the street during storm.	1,000	Overflow stopped following heavy rain event.	Monitored site.	614970
13	9/9/2018	1800 E Eager St	21205	Rags, Rain, Infiltration, Trash	Wet	N/A	535	Surcharging manhole due to heavy rain.	769,000	Monitored the area; overflow stopped after heavy rain event.	Location is equipped with an Event Notification System meter.	615044
14	9/9/2018	1731 E Chase St	21205	Rags, Rain, Infiltration, Trash	Wet	N/A	530	Surcharging manhole due to heavy rain.	310,000	Monitored the area; overflow stopped after heavy rain event.	Location is equipped with an Event Notification System meter.	615040
15	9/9/2018	1901 Falls Rd	21218	Rain, Trash	Wet	N/A	820	Manhole surcharging due to heavy rain event.	722,000	Overflow subsided following heavy rain event.	Location is monitored by an Event Notification System.	615035
16	9/9/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	915	Structure monitored by metering equipment in pipe.	5,600,000	SSO structure. Not applicable.	Structure is monitored by metering equipment in the pipe. No photo available.	
17	9/9/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	1285	Structure monitored by metering equipment in pipe. Not visually observed.	17,046,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
18	9/9/2018	3104 Liberty Heights Ave - SSO Site #135	21215	Rain	Wet	Gwynns Falls	405	Structure monitored by metering equipment in pipe. Not visually observed.	3,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
19	9/9/2018	Queensberry Ave & W Garrison Ave - SSO Site #139	21215	Rain	Wet	Jones Falls	75	Structured overflow discharging to a nearby storm drain.	2,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
20	9/11/2018	3602 Cottage Ave	21215	Rags, Roots	Wet	N/A	0	Water and debris observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	616242

## SSO Notification List

SEPTEMBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	9/12/2018	1822 E 29th St	21218	Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with electric cable.	Performed CCTV inspection.	616479
22	9/12/2018	1001 N Ellamont St	21216	Rags, Roots, Grease, Trash	Wet	N/A	330	Heavy gray water escaping manhole.	8,250	Relieved 8" mainline choke with 300 ft of pressure hose.	Performed mainline CCTV inspection; confirmed line is clear.	616517
23	9/12/2018	3528 Esther Pl	21224	Rags, Trash, Structural	Wet	N/A	0	Gray water and debris observed on the ground.	3	Flushed and cleaned 8" mainline with 300 ft of pressure hose.	Performed CCTV inspection to investigate potential structural damage to pipe.	616749
24	9/13/2018	725 Gorsuch Ave	21218	Rags, Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed connection is clear.	617205
25	9/13/2018	428 E Preston St	21202	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	617014
26	9/14/2018	1247 Walker Ave	21239	Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	4	Relieved house connection choke with 45 ft of electric cable.	Confirmed connection is clear.	617357
27	9/15/2018	600 Hilton Pkwy	21229	Rags, Trash, Sand, Gravel, Rocks	Dry	N/A	2527	Heavy gray water escaping the manhole.	12,635	Relieved mainline choke with 350 ft of pressure hose.	Confirmed mainline is clear.	617813
28	9/17/2018	2207 Homewood Ave	21218	Grease, Trash	Wet	N/A	0	Gray water & debris observed around the cleanout.	1	Relieved house connection choke with 13 ft of electric cable.	Performed CCTV inspection.	618044
29	9/18/2018	1901 Falls Rd	21218	Rags, Roots, Rain, Grease, Trash	Wet	N/A	0	Heavy gray water observed around manholes.	25	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	618247
30	9/18/2018	1744 E Lafayette Ave	21213	Rags, Trash	Wet	N/A	0	Evidence of sewer overflow observed around the cleanout.	5	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	618380
31	9/18/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	905	Structure monitored by metering equipment in pipe.	3,074,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
32	9/18/2018	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	220	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe. Not visually observed.	132,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
33	9/18/2018	N Charles St & Lafayette Ave - SSO Site #154	21202	Rain	Wet	Jones Falls	250	Structure monitored by metering equipment in pipe.	42,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
34	9/18/2018	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	160	Structure monitored by metering equipment in pipe.	84,000	SSO structure. Not applicable.	Structure is monitored by metering equipment in the pipe. No photo available.	
35	9/18/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	1130	Structure monitored by metering equipment in pipe.	14,961,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
36	9/18/2018	3104 Liberty Heights Ave - SSO Site #135	21215	Rain	Wet	Gwynns Falls	145	Structure monitored by metering equipment in pipe.	5,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
37	9/18/2018	410 N Rock Glen Rd	21229	Rags, Roots, Trash	Wet	N/A	66	Gray water escaping the cleanout at the front of the property.	66	Relieved house connection choke with 45 ft of electric cable.	Confirmed connection is clear.	618547
38	9/18/2018	402 Key Hwy	21230	Rags, Grease, Trash	Wet	N/A	113	Water escaping the manhole in the street.	226	Relieved 8" mainline choke with 100 ft of pressure hose.	Performed CCTV inspection.	618568
39	9/18/2018	Kirk Ave & Exeter Hall Ave	21218	Structural	Wet	N/A	650	Gray water observed on the street.	3,250	Set up traffic pattern and performed CCTV inspection to determine cause.	Engineering is investigating to determine possible structural damage.	618577
40	9/18/2018	1731 E Chase St	21213	Rain	Wet	N/A	135	Water escaping the manhole in the street.	174,000	Overflow subsided following heavy rain event.	This location is equipped with an Event Notification System meter.	618173
41	9/18/2018	1800 E Eager St	21205	Rain	Wet	N/A	200	Water surcharging from manhole due to heavy rain event.	188,000	Flow returned to normal following heavy rain event.	Location is equipped with an Event Notification system meter.	618170

## SSO Notification List

SEPTEMBER 2018

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
42	9/18/2018	1901 Falls Rd	21218	Rain	Wet	N/A	855	Water escaping from manhole in the street.	330,000	Conditions returned to normal following heavy rain event.	Location is equipped with an Event Notification System meter.	618168
43	9/18/2018	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	175	Structure monitored by metered equipment in the pipe. Not visually observed.	5,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
44	9/21/2018	436 Kane St	21224	Trash	Wet	N/A	117	Gray water escaping manhole.	1,755	Relieved 8" mainline choke with 70 ft of pressure hose.	Confirmed mainline is clear.	619909
45	9/22/2018	2313 Allendale Rd	21216	Rags, Roots, Grease	Dry	N/A	0	Gray water and debris observed around the cleanout.	5	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	620117
46	9/24/2018	4213 Menlo Dr	21215	Rags, Trash	Wet	N/A	0	Water and debris observed around the cleanout.	5	Relieved 6" house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	620458
47	9/25/2018	1919 Fairbank Rd	21209	Rags, Trash, Sand, Gravel, Rocks	Wet	N/A	106	Gray water escaping from manhole.	159	Relieved 8" mainline choke with 150 ft of pressure hose.	Confirmed mainline is clear.	620769
48	9/26/2018	3648 Beech Ave	21211	Rags, Roots, Trash	Wet	N/A	0	Water and debris observed around the cleanout.	1	Relieved 6" house connection choke with 30 ft of electric cable.	Confirmed mainline and lateral are clear.	621152
49	9/27/2018	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	870	Structure monitored by metering equipment in pipe.	1,461,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
50	9/27/2018	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	1050	Structure monitored by metering equipment in pipe.	13,180,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
51	9/28/2018	3104 Liberty Heights Ave - SSO Site #135	21215	Rain	Wet	Gwynns Falls	60	Structure monitored by metering equipment in pipe.	2,000	SSO structure. Not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
52	9/29/2018	5740 Cross Country Blvd	21209	Rags, Roots	Wet	N/A	124	Gray water escaping the mainline.	372	Relieved mainline choke with 200 ft of pressure hose.	Performed CCTV inspection; confirmed mainline is clear.	622326
53	9/29/2018	926 Greenmount Ave	21202	Rags, Structural	Wet	N/A	683	Heavy gray water escaping the cleanout.	683	Relieved house connection choke with 45 ft of electric cable. Repaired damage to lateral.	Performed CCTV inspections on mainline and house connection.	622427
				# WWO	40			TOTAL	58,234,983	UNDER 100 GALLONS	23	