

SSO Notification List

September 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	9/1/2020	3130 Guilford Ave	21218	Rags, Unknown	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Ran electric cable through the lateral; blockage remained. Flushed and cleaned mainline.	Further investigation will take place via CCTV inspection once line is pumped down.	881077
2	9/3/2020	1601 Waverly Way	21239	Sand, Gravel, Rocks, Unknown	Wet	N/A	0	Gray water observed in the woods.	15	Flushed the mainline; blockage and/or structural damage remained.	Further investigation will take place, including a CCTV inspection.	881409
3	9/3/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	95	Manhole adjacent to creek overflowed due to heavy rain.	501,000	Overflow subsided following heavy rain event.	SSO will be prevented after completion of capital improvement projects.	
4	9/3/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	95	Structure monitored by metering equipment in the pipe. Not visually observed.	2,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
5	9/3/2020	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	50	Structure monitored by metering equipment in pipe.	500	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
6	9/4/2020	1737 Waverly Way	21239	Rags, Grease, Trash	Wet	Herring Run	10208	Sewage overflowing into Herring Run from manhole in the woods.	2,041,600	Contractor jetted the line to relieve the choke and abate the overflow.	CCTV inspection will be performed. Abatement confirmed via Office of Compliance and Laboratories.	881523
7	9/4/2020	2411 Harriet Ave	21230	Rags, Trash, Sand, Gravel, Rocks	Wet	N/A	0	Gray water and paper observed around the cleanout.	2	Ran 60 ft of electric cable through the lateral; flushed and cleaned the 8" mainline with 200 ft of pressure hose.	CCTV inspection will be performed to determine if further blockage remains.	881566
8	9/4/2020	Harford Rd & Walther Ave	21206	Trash	Wet	N/A	0	Gray water observed around the manhole.	2	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed.	881561
9	9/5/2020	616 Woodbourne Ave	21212	Rags, Trash, Unknown	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Ran 35 ft of electric cable through the lateral; some blockage remained.	Further investigation will take place, including performing a CCTV inspection.	881648
10	9/6/2020	Hilton Pkwy & W North Ave	21216	Rags, Roots, Grease, Trash	Wet	N/A	162	Gray water escaping the manhole.	810	Relieved mainline choke with 15 ft of pressure hose.	CCTV inspection will be performed.	881684
11	9/9/2020	York Rd & E Cold Spring Ln	21212	Structural	Dry	Tiffany Run	19570	Suspected broken sanitary mainline leaking into storm drain. Found during routine sampling.	9,785	Contractor lined the pipe to stop the leak and abate the subsurface overflow.	Performed dye testing to confirm sewage is no longer infiltrating the storm drain.	881937
12	9/9/2020	915 Seagull Ave - (Private)	21225	Rags, Grease, Trash	Dry	N/A	41	Gray water escaping privately-owned manhole.	410	Assisted by relieving mainline choke with 150 ft of pressure hose.	Confirmed mainline is clear.	881977
13	9/9/2020	Harford Rd & Walther Ave	21214	Structural	Dry	N/A	8687	Sanitary sewer broken by contractor on a construction site.	43,435	Contractor made repairs to stop the overflow and restore line to regular functionality.	Confirmed sewage is no longer escaping the system.	881930
14	9/10/2020	2607 Jefferson St	21224	Rags, Trash	Wet	N/A	0	Gray water observed in the rear alley.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	882143
15	9/11/2020	430 E Preston St	21202	Trash, Other	Wet	N/A	0	Gray water observed around the area.	5	Flushed and cleaned the mainline. Ensured nearby pump is functioning correctly.	Location has a pump working nonstop to handle flow from these lines.	882222
16	9/11/2020	264 S Loudon Ave	21229	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed line is clear.	882316
17	9/11/2020	1008 N Franklinton Rd	21216	Grease, Trash, Sand, Gravel, Rocks	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	882335
18	9/12/2020	52 N Bentloul St	21223	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	882385
19	9/15/2020	3421 Olympia Ave	21215	Structural	Dry	N/A	10762	Suspected broken sanitary line leaking into storm drain. Found during routine sampling.	2,691	City construction crews repaired the broken line.	Confirmed via dye testing that the line is no longer leaking sewage into the storm drain.	
20	9/15/2020	6301 Yorkshire Dr	21212	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	882627
21	9/16/2020	1000 N Eutaw St	21201	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole.	7	Relieved mainline choke with 125 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	882739

SSO Notification List

September 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	9/16/2020	1029 W 36th St	21211	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	882841
23	9/16/2020	3415 Holmes Ave	21217	Rags, Roots, Grease	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	882831
24	9/16/2020	2315 Lipps Ln	21223	Rags, Trash	Dry	N/A	0	Heavy gray water observed on the sidewalk.	8	Relieved choke with 75 ft of electric cable.	Confirmed line is clear; CCTV inspection will be performed.	882889
25	9/16/2020	1011 W 37th St	21211	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed.	882804
26	9/19/2020	821 W Lake Ave	21210	Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; line will be cleaned.	883224
27	9/21/2020	2500 Shirley Ave	21215	Rags, Grease, Trash	Dry	N/A	75	Gray water escaping the manhole.	75	Relieved mainline choke with 100 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	883294
28	9/22/2020	131 W Lanvale St	21217	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 40 ft of electric cable.	Confirmed line is clear; CCTV inspection will be performed.	883434
29	9/22/2020	W North Ave & Hilton Pkwy	21216	Rags, Grease, Trash	Dry	Gwynns Falls	77	Heavy gray water escaping the manhole.	385	Relieved mainline choke with 25 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	883459
30	9/23/2020	2248 Madison Ave	21217	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	883691
31	9/24/2020	532 W Hoffman St - (Private)	21201	Rags, Grease, Trash	Dry	N/A	89	Gray water escaping the manhole.	890	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear.	883731
32	9/24/2020	2028 N Calvert St	21218	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed.	883864
33	9/26/2020	3159 Ravenwood Ave	21213	Rags, Roots	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	884127
34	9/27/2020	613 Reservoir St	21217	Rags, Roots	Wet	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 35 ft of electric cable.	Confirmed lateral and mainline are clear.	884174
35	9/28/2020	3033 Ascension St	21225	Rags	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	884309
36	9/29/2020	908 Chestnut Hill Ave	21218	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	884459
37	9/30/2020	1123 Belmore Ave	21210	Rags, Roots, Grease	Wet	N/A	0	Gray water observed at the rear of the property.	5	Relieved mainline choke with 150 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	884561
				# WWO	20			TOTAL	2,602,359	UNDER 100 GALLONS	26	