

## SSO Notification List

September 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	9/1/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	40	Structure monitored by metering equipment in the pipe. Not visually observed.	87,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
2	9/1/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	400	Structure monitored by metering equipment in the pipe. Not visually observed.	1,699,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
3	9/1/2021	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	260	Structure monitored by metering equipment in the pipe. Not visually observed.	34,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	
4	9/6/2021	4803 Roland Ave	21210	Rags, Roots, Grease, Trash	Dry	Jones Falls	0	Gray water observed on the sidewalk.	5	Flushed the 6" mainline with 490 ft of pressure hose.	CCTV inspection will be performed to determine further action.	971596
5	9/7/2021	2844 Hinsdale Dr	21230	Rags	Dry	N/A	0	Gray water and debris observed around the cleanout.	1	Ran 45 ft of electric cable through the lateral.	Flushed and cleaned the 8" mainline.	971897
6	9/8/2021	1130 Myrtle Ave	21201	Rags, Structural	Dry	N/A	0	Gray water observed at the rear of the property.	1	Partially relieved house connection choke with 25 ft of electric cable.	Lateral launch will be performed to ensure line is fully cleared.	971956
7	9/8/2021	2012 E Lafayette St	21213	Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Maintenance crew relieved house connection choke with electric machine cable.	Crew CCTV'd lateral and results showed connection to mainline clear.	972093
8	9/9/2021	6608 Danville Ave	21224	Rags, Roots	Wet	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Nearby tree is causing roots to infiltrate the line. Location placed on routine cleaning.	972322
9	9/9/2021	1614 N Pulaski St	21217	Rags, Grease, Trash	Wet	Gwynns Falls	401	Gray water escaping the manhole in the street.	802	Relieved mainline choke with 350 ft of electric cable.	Performed CCTV inspection and determined the line is now clear.	972561
10	9/11/2021	907 W 34th St	21211	Trash, Sand, Gravel, Rocks	Wet	N/A	0	Heavy gray water observed around the manhole.	10	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed to determine if any structural damage exists in the pipe.	972982
11	9/13/2021	6608 Harford Rd	21214	Rags, Roots	Dry	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection and results showed the line to be clear.	973287
12	9/13/2021	3803 Clarks Ln - Private	21215	Rags, Trash	Dry	Jones Falls	117	Sewage discharging from private, illegal sump pump and running into the alley.	234	DPW relieved private house connection choke with 75 ft of electric cable.	Investigator has referred this location to housing code enforcement.	973236
13	9/13/2021	6513 Fairdel Ave	21206	Rags, Trash	Dry	Moores Run	353	Subsurface overflow into storm drain system discovered during routine survey sampling.	706	Relieved mainline choke with 300 ft of pressure hose.	Dye testing confirmed the SSO is no longer occurring.	973365
14	9/14/2021	3502 Chestnut Ave	21211	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear.	973722
15	9/15/2021	500 W University Pkwy	21210	Rags, Roots, Trash	Dry	N/A	301	Heavy gray water escaping the manhole and entering nearby waterway.	7,525	Relieved mainline choke with 450 ft of pressure hose.	Confirmed the mainline is clear at this time. A CCTV inspection will be performed.	973794
16	9/15/2021	1204 Seminole Ave	21229	Structural	Dry	Gwynns Falls	105	Gray water escaping a mainline in nearby wooded area.	105	A brace was resecured on the line to stop the leak.	Line was restored to regular functionality.	973839
17	9/16/2021	4001 Glenmore Ave	21206	Structural	Dry	Herring Run	30716	House connection is leaking, allowing sewage to escape to storm drain.	7,679	Contractor replaced 25 ft of pipe to restore lateral to regular functionality.	Dye testing confirmed the leak is no longer taking place.	974030
18	9/16/2021	700 Baylis St	21224	Roots	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear at this time.	974180
19	9/19/2021	1533 Barclay St	21202	Roots	Wet	N/A	0	Gray water observed around the rear cleanout.	1	Relieved house connection choke with 15 ft of electric cable.	Confirmed both lateral and mainline are now clear.	974746
20	9/20/2021	206 Woodlawn Rd	21210	Roots	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	974765

## SSO Notification List

September 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	9/20/2021	3207 Yosemite Ave	21215	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear; CCTV inspection will be performed.	975066
22	9/22/2021	4106 Potter St	21229	Rags, Roots, Grease, Trash	Dry	Gwynns Falls	78	Heavy gray water escaping the manhole and entering nearby waterway.	1,950	Relieved mainline choke with 100 ft of pressure hose.	Confirmed the line is now flowing freely; CCTV inspection will be performed.	975570
23	9/23/2021	1618 N Pulaski St	21217	Rags, Rain, Grease	Wet	Gwynns Falls	236	Heavy gray water escaping the manhole and entering nearby storm drain.	5,900	Relieved 15" mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	975995
24	9/23/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	110	Structure monitored by metering equipment in the pipe. Not visually observed.	160,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
25	9/25/2021	4016 Pinkney Rd	21215	Rags, Grease, Trash	Wet	Gwynns Falls	0	Gray water observed around the sump pump and storm drain.	5	Relieved mainline choke with 350 ft of pressure hose.	Confirmed the line is clear at this time; CCTV inspection will be performed.	976440
26	9/25/2021	1200 Poplar Hill Rd	21210	Rags, Roots	Wet	Jones Falls	0	Gray water and paper observed around the cleanout.	3	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and results confirmed the lateral is clear.	976460
27	9/27/2021	4803 Roland Ave	21210	Roots, Structural	Dry	N/A	0	Gray water observed around the lamphole.	2	Construction crew repaired damaged 6" mainline.	Confirmed line is restored to regular functionality.	976756
28	9/27/2021	5110 Ardmore Way	21206	Rags, Roots, Grease	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and informed consumer of non-flushable material.	976717
29	9/28/2021	3008 Parkside Dr	21214	Roots	Dry	N/A	0	Gray water observed on the front sidewalk.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed both the lateral and mainline are now clear.	977008
30	9/28/2021	2400 Brentwood Ave	21218	Rags, Roots	Dry	N/A	0	Heavy gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral is clear at this time.	977075
31	9/28/2021	4408 Marble Hall Rd - Private	21239	Structural	Dry	Jones Falls	4293	A private sewer mainline was struck by nearby construction and is discharging.	21,465	Broken sewer line was replaced to restore line to regular functionality.	DPW assisted to ensure private line was installed correctly and area was cleaned.	997097
32	9/30/2021	Rusk Ave & Wetherburn Rd	21209	Rags, Roots, Grease	Dry	Jones Falls	121	Gray water escaping the manhole and entering nearby storm drain.	242	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now flowing freely; CCTV inspection will be performed.	977438
33	9/30/2021	101 Cotswold Rd	21210	Rags, Roots	Dry	N/A	0	Gray water and paper observed around the cleanout.	2	Relieved house connection choke with 60 ft of electric cable.	CCTV inspection results confirmed the line is clear.	977645
				# WWO	11			TOTAL	2,004,951	UNDER 100 GALLONS	19	