

SSO Notification List

September 2022

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	9/1/2022	261 W 31st St	21211	Roots	Wet	N/A	—	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	1134523
2	9/3/2022	715 Woodbourne Ave	21212	Rags	Dry	N/A	—	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	—
3	9/4/2022	219 S President St	21202	Grease, Sand, Gravel, Rocks	Dry	Northwest Harbor	50	Gray water escaping the cleanout from side of the property.	25	Relieved choke with pressure hose and electric cable.	CCTV inspection will be performed to determine if further action is needed.	1135164
4	9/5/2022	4300 Keswick Rd	21210	Rags, Trash	Dry	N/A	—	Gray water observed around the manhole.	3	Relieved mainline choke with 300 ft of pressure hose.	Mainline CCTV inspection will be performed.	1135200
5	9/6/2022	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	130	Structure monitored by metering equipment in the pipe. Not visually observed.	271,050	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
6	9/6/2022	202 S Athol Ave	21229	Rags, Grease	Wet	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and determined the lateral is clear.	1135239
7	9/6/2022	813 Bradhurst Rd	21212	Rags	Wet	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection; line is now clear.	1135518
8	9/11/2022	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	70	Structure monitored by metering equipment in the pipe. Not visually observed.	6,020	SSO structure; not applicable.	SSO structure will be closed upon completion of capital improvement projects.	—
9	9/13/2022	2 N Bentalou St	21223	Roots	Wet	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV confirmed the mainline and lateral are clear.	1137815
10	9/18/2022	1304 Asbury Rd	21209	Roots	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are now both clear.	1139403
11	9/19/2022	2518 E Madison St	21205	Roots, Grease	Dry	N/A	—	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	1139588
12	9/20/2022	4600 Hampnett Ave	21214	Rags, Grease	Dry	N/A	—	Gray water and debris near the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection.	1140440
13	9/22/2022	2601 N Hilton St	21216	Rags, Roots, Grease	Dry	Gwynns Falls	25	Choked sewer discharging into adjacent storm drain pipe.	250	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to determine if further action is needed.	1140822
14	9/22/2022	4715 Norwood Ave	21207	Structural	Dry	Gwynns Falls	26224	Sewer overflowing subsurface into adjacent storm pipe.	26,224	Mainline was repaired to restore system to regular functionality.	Abatement confirmed via the Office of Compliance and Research.	1140863
15	9/23/2022	4610 Springdale Ave	21207	Structural	Dry	Gwynns Falls	222372	Wastewater leaking from sewer segments and infiltrating the storm drain subsurface.	55,593	Contractor lined the pipe to stop the leak from occurring.	Lining restored the sewer mainline to regular flow.	1141236
16	9/27/2022	128 Kane St	21224	Rags, Roots, Trash	Wet	N/A	—	Gray water observed around the manhole.	3	Relieved mainline choke with 250 ft of pressure hose.	Confirmed the mainline is clear; CCTV inspection will be performed.	1142298
17	9/28/2022	2410 Loyola Northway	21215	Rags, Roots, Grease	Dry	N/A	—	Heavy gray water observed around the manhole cover.	3	Relieved mainline choke with 100 ft of pressure hose.	Mainline CCTV inspection will be performed.	1142726
				# WWO	7			TOTAL	359,179	UNDER 100 GALLONS	12	